


# Village of Lake Barrington, Illinois Pavement Management Report

Exhibit 1  
Rehabilitation Strategy



LLBARR050076-GISE/Exhibit 1 - Rehabilitation Strategy.mxd  
Date: Aug 15, 2006 By: SLN



### Rehabilitation Strategy

- No Work
- Minor Patching & Overlay
- Major Patching & Overlay
- Major Patching ( $\geq 100\%$ )
- Full Width Sur. R/R & Base Repair

Village Limits

0 1,000 2,000 3,000 Feet